


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-193	Smoke	7/27/2009	ADS/TM	S17AA_039MH	Dry	Yes	361.97



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-193	Smoke	7/27/2009	ADS/TM	S17AA_039MH	Dry	Yes	361.97

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S17AA_039G1	S17AA_039MH	S15AA_040MH	175.562	8
S17AA_040G1	S17AA_040MH	S17AA_039MH	186.408	8

Observations & Photos

Obs_ID S1028-193-OB01

Address 2519 Mosher St.


Status Private

Source Cleanout

Location Yard - back

Nearest MH S17AA_039MH

Comments Smoke from cleanout in back yard. 2519 Mosher St.



Picture \S1028-193-OB01-P01.jpg

Comments Back of house, 2519 Mosher St.

